

[About Us](#)[Commercial](#)[Residential](#)[Testimonials](#)[Our Team](#)[Contact Us](#)

Project Name: Best Buy Downers
Grove #301

Date: 12/26/2013

Inspection Time: 10:00

Building Information

GPS Location: Lat:41.836506,Lon:-88.019249,Acc:65.000000



Item of Inspection: Old skylight lens that has failed.



Photo 1 Notes: Removed old skylight. all materials will be hoisted with Local Roofing crane, fall protection will be required at all times.



Photo 2 Notes: Installed new gasket before install of new skylight lens. Fastened with tech # (3) fasteners.

Item of Inspection: Old skylight lens.



Photo 1 Notes: Removed old skylight. (Two Total)



Photo 2 Notes: Installed new gasket at top of curb before installing new lens and fastening.

Item of Inspection: Other repairs



Photo 1 Notes: Due to severe winds Hvac unit door had blown off.



Photo 2 Notes: Re installed door.

Item of Inspection: upon the install of the new skylight lenes; found a puncture in roof's membrane.



Photo 1 Notes: Found large puncture in roof's membrane. Removed snow, ice, and cleaned area.



Photo 2 Notes: Installed white granulated modified to match existing roof system. All work completed per the manufactures specifications.

Local Roofing Co. Inc. was founded in 1952 and over the past 59+ years has grown into one of the leading Northern Illinois Commercial, industrial, and residential roofing companies. We have the practical experience and solutions for your roofing issues and concerns. We have an office staff and experienced roof technicians to meet all your roofing needs.